

## MTC - FINGER INJURY BY USE OF PULL / PUSH HAMMER

### BESKRIVELSE AV HENDELSE (HVA?):

Reassembly of fluid end on HP pump whilst using sliding hammer ,The IP right hand ring finger squeezed on fwd motion impact on the steel hammer ring. Minor fracture and stitches needed

### ÅRSAK (HVORFOR?)::

Hand slipped

equipment had been rinsed prior to reassembly but mud was still present , impact gloves were wiped frequently but they were still slippy as was the tool

### LÆRING ETTER HENDELSE:

We are looking into a modified/better tool to use fore this kind of work with bigger safety guard mounted on



### DETALJER:

**Rapport-ID:** 1718509

**Lokasjon:** Offshore

**Område:** Drilling

**Type arbeid:** Operasjon / Drift

**Type hendelse:** Personskade

**Dato for hendelse:** 2017-05-23

