

## PARTED CASING SLING.

### EVENT DESCRIPTION (WHAT?):

While bundling up 10" casing joints for backload one of the casing slings ( WLL 4 tons ) parted.

synergi 1720014

### CAUSES (WHY?):

Indications show that the casing sling caught up on the edge of one Samson post supports. And that it parted when tightened up.

### LESSON LEARNED:

Be observant and check slings before lifting.

Look at guard for samson post feet and flat iron mounting points for pipe cradles



### DETAILS:

**Report ID:** 1720014

**Location:** Offshore

**Area:** Transportation

**Type of work:** Crane and Lifting

**Type of lesson:** Barrier degradation

**Date of incident:** 2017-05-26

**Unit:** Maersk Intrepid

